




SNOW CONE



SNOW CONE

INSTRUCTIONS:

1. Turn POWER switch ON.
2. Fill the ice horn with ice.
3. Press and hold the MOTOR switch to activate blades and begin shaving ice.
4. While holding MOTOR switch down, apply steady downward pressure to the ice pusher.
5. Release the MOTOR switch when finished.
6. Repeat steps 2-5 for additional batches.

For return, please note that the machine must be clean or a cleaning fee will added.